

Asbestos Sample Collection & Analysis Report

Due Diligence Asbestos Inspection & Testing

Report Number: Your Reference: Issue Date: 3904.01.ASN Rev 0 QM 3220224 4 October 2023

Prepared For	Site Location	Investigated by	
Adal Home 6/25 Perpetual St, TRUGANINA, VIC 3029	The Cargo Warehouse, 557 Mt Derrimut Rd, DERRIMUT, VIC 3030	Michael Tierney BE Director Asbestos Assessor (License No. LAA001018)	
Investigation Date: N	Monday, 2 October 2023		

1 Scope

Greenlight Environmental Services Pty Ltd (Greenlight) was engaged by Kien Huynh of Adal Home to attend the above-mentioned site to collect four (4) samples for the analysis of asbestos content.

2 Sample Collection and Analysis Method

The samples were analysed under a Stereomicroscope and selected fibres were analysed by Polarised Light Microscopy in conjunction with dispersion staining techniques including Synthetic Mineral Fibre and Organic Fibre as per the Australian Standard AS 4964-2004 Method for the qualitative identification of asbestos in bulk samples.







Sample Collection Details 3



	Asbestos Extent: Asbestos Items: High Risk Items:	None None None		Inspected on Inspected by	2 October 2023 Michael Tierney BE Director Asbestos Assessor (License No. LAA001018)
Location	Assessment Det	ails Risk		Photo	Controls
The Cargo Warehouse - Crate	e D12				
Stone Veneer Black vinyl with fibre reinforcement	Method Sampled (GL Outcome Synthetic Mir Fibres (No As Detected	neral	R		
Stone Veneer Grey vinyl with fibre reinforcement	Method Sampled (GL Outcome Synthetic Mir Fibres (No As Detected	neral			

Report : 3904.01.ASN Rev 0 - Asbestos Sample Collection & Analysis Report

Site : The Cargo Warehouse





	Location	Asses	sment Details	Risk	Photo	Controls	
Th	The Cargo Warehouse - Crate D12 (continued)						
	Stone Veneer Dark Grey vinyl with fibre reinforcement	Method Outcome	Sampled <i>(GL011090)</i> Synthetic Mineral Fibres (No Asbestos) Detected	No Asbestos Risk Identified			
Th	The Cargo Warehouse - 2x Smaller Crates						
	Concrete Finish Veneer Medium grey vinyl with fibre reinforcement	Method Outcome	Sampled <i>(GL011091)</i> Synthetic Mineral Fibres (No Asbestos) Detected	No Asbestos Risk Identified			

Report : 3904.01.ASN Rev 0 - Asbestos Sample Collection & Analysis Report

Site : The Cargo Warehouse





4 Site Photos





Figure 1 – Larger crate with stone veneer finish vinyl product



Report: 3904.01.ASN Rev 0 - Asbestos Sample Collection & Analysis ReportSite: The Cargo Warehouse





Figure 2 – Larger crate with concrete veneer finish vinyl product

ADDRESS TON BROATS TRUGATION	0.23 EL
CRV 3220224 Participation of the second seco	
ASBETUS TESTING ASBETUS TESTING MARKING MARKAN ASSHIPPED MARKAN M	10 723 10 723 10 723
Sana Da	

Figure 3 – Transfer of Goods receipt

5 Limitations

The investigation was directed towards specific items on the property as directed by the client – this document therefore does <u>not</u> constitute a Division 6 or Division 5 Asbestos Register as is required by the OHS Regulations 2017 for workplaces or for refurbishments carried out by a commercial company or as is required for any demolition works.

Please note that this legal requirement <u>does</u> apply to private residences, where:

- The property is being refurbished by an individual or company other than the owner of the property, or:
- The property is undergoing demolition.

Under these circumstances the property is then considered to be a workplace and the requirements of the OHS Act 2004 will then apply (i.e. an asbestos register is required, prior to any works commencing).

Report : 3904.01.ASN Rev 0 - Asbestos Sample Collection & Analysis Report Site : The Cargo Warehouse





The required asbestos register for such circumstances must include an assessment of the whole property or area to be refurbished by an independent and qualified investigator such as Greenlight.

Additionally please note that while all work is performed to a professional and diligent standard by competent, trained and qualified staff members, the potential variance between the cost of our services, all possible issues of concern, and any loss or damages which may be associated with our work are such that we cannot warrant that a particular sample is typical of an extended area. We therefore limit any potential liability associated with our work to the cost of our services.

Kind Regards,

Michael Tierney BE Director Asbestos Assessor (License No. LAA001018)

QA/QC by:

Chloe-Rose Simpson Administration Manager

Report: 3904.01.ASN Rev 0 - Asbestos Sample Collection & Analysis ReportSite: The Cargo Warehouse